GENERAL AND REVENUE SECRETARIAT.

1896-1897

~~19~~

(Muzrai)

File No. 48

(Section II)

Serial Nos.

Papers Filed.

Month ~~January~~ 1905

SUBJECT.

File relating to The repairs of the Sri Tamara Swami and Sri Sakkleswara Swami Temples at Mandya Town.

PREVIOUS REFERENCES.	LATER REFERENCES.

order

The accompanying Estimate amounting to Rs 565 for repairing the Sri Jawarthana Swamie Temple at Inuvidya which has been prepared under the orders of the Inuvrai Superintendent is sanctioned, the charge being met from the State Grant of Rs 15000 sanctioned in Govt Pro No. 1083 dated 29th March 1899 Inuv 7 105-92 for the repairs of Inuvrai Buildings in the Province during the year 1899-1900.

2. The amount sanctioned in the foregoing para will be paid on presentation to the Comptroller of a bill duly signed by the Inuvrai Superintendent.

No 119 / En. 1

Dy 29.7.99.

To,
The Comptroller
to Government.

Inuvrai Secretary

Mandya Taluq

Estimate of the Probable cost of Improving & repair Janardhana Swamies Temple at Mandya.

Details of work	No.				
Fixing 2 windows in the Nave 3'×6' excluding frames for glass Shutters inside and wooden shutters outside with Iron Bars 1" in Dia. with Iron works & Painting &c.					
Complete — No.	2				2
Diamanthing					
walls for the above —	2	4½	3½	2	63
Total C.					63
Concrete:-					
flooring 3" Thick Lower floor.	1	29	18	3"	130
— Do — Upper floor —	1	29	6'	3"	47
— Do — Do —	1	18	10	3"	45
Total C. ft.					222
Brick in Chunnam:-					
Top of Navaranga Temple:-					
Parapet Wall —	1	7	1'	1'	16
— Do —	2	5	1½	1'	23
Dhwajastamba Temple.	1	45	1'	1'	101
Do —	1	30	1½	1½	78
Do —	1	20	1'	1'	45
Total C. feet					263
Plastering with Chunam:-					
— Do. Parapet walls.	1	112	u	4'	504

Roof of Dhwajastambha Temple

Concrete.— —— Do —— | 1 | 45 | 30 | 3 | 33¾

Total C ft. 338

Sundry:- Sundry Repairs such as white washing repairing the floor of Navaranga Temple and Pointing the Joints of the Talabotte —— | | | | | | Ls

Teak wood Door (battened) 6'x4'x(1½") with Locketc everything complete —— | 1 | 6' | 4' | 1½ | 24

Total Sqr. ft. 4

Repairing the Leaks of Thayar Samadhi and white washing the whole Temple and Repairing floor etc —— | | | | | | Ls 5

Sultan, a Teak wood Door with Iron works complete —— | | | | | | Ns 30

Compensation for acquiring the House adjoining the Temple as settled by the Amuldar —— | | | | | | 100.

Compound wall:-

—— Do —— In continuation of the existing walls as detailed below:-

Excavating foundation —— | 1 | 17 | 2 | 5 | 170

Total Cy Ft.

Rough stone in hand:-

Filling foundation as above —— | | | | | | 170

Total C. ft. 170

Bricks in hand.-

Superstructure —— | 1 | 17 | 11 | 6 | 153

Repairing the Compound wall - 80

Total C ft. 233

Plastering

Northern Side Compound wall | 1 | 100 | 4 | - | 400

West - Do —— | 1 | 110 | 4½ | - | 495

South | 1 | 50 | 3 | | 150

New wall —— | 1 | 17 | 3½ | | 229

12 4

Abstract.

Names of work	Per	Rate	Qr	Cost.		
Fixing teak wood windows as in the body	Each	20	"	"	2	40 " "
Dismantling	C/t	"	"	3	63	1 " "
Concret	C/t	"	2	6	560	88 " "
Brick in Chunam	"	"	2	9	26	4 " "
Plastering in Chunam	Sq	2	12	"	177	49 .
Sundry repairs such as white washing repairing the floor of havancing a temple &c &c	L					50 " "
Teak wood door as per detail	S	1	"	"	24	24 " "
Repairing the leaks of Thayar Sanathi and white washing the whole Temple &c						7 " "
Compensation						100 "
Excavating foundation for impound wall.	Cyd	"	2	"	7	1 .
Rough stone in mud for do	"	"	1	3	170	13 " "
Brick in mud for do	"	"	1	9	233	24 " "
Putting a teak wood doors for Thay Sanathi						30 "
Total Rupees						540 " "
Contingencies at 5% Rupees						2
Grand Total						56

No 120
Exn.
Dt 29.7.99

Order

The accompanying Estimate amounting to Rs 105 for repairing the Sri Sakleswara Swamy temple at Mandya which has been prepared under the orders of the Kuvrai Superintendent is sanctioned, the charge being met from the State Grant of Rs 15000 sanctioned in Govt Pro No 1083 dated 29th March 1899 Kuvr 7 105-92 for the repairs of Kuvrai Buildings in the Province during the year 1899-1900.

2. The amount sanctioned in the foregoing case will be paid on presentation to the Comptroller of a bill duly signed by the Kuvrai Superintendent

Kuvrai Secretary

To,
The Comptroller
to Government.

Kanaya Sahib.

Estimate of the probable cost for Repairing the Sakalesvara swamy Temple at Belur

Ref 1900 -

Details of work	Nos	Dimensions L	B	H	Contents	Total
Teak wood Shutter to window	2	2½	3	(1")	15	15
2 Jungle wood doors one for Ganeshaguddy (1 × 6' × 3¾) and another Vishwanathaguddy (1 × 5' × 3½) with Locks and Iron hooks Complete each	Amp	Amt			Rs	16
Parvathiswamy's Temple.						
Brick in Chunam						
Superstructure	1	10	1½	8	120	
Parapet-wall on Top	1	10	1⅛	½	17	
Total Cft.					137	
Deduct for door way	1	5½	1½	3	25	
Balance brick in Chunam	Cft					102.
Plastering						
All round	1	10	16	-	160	
Sundry here and there	Amp	quantity			140	
Total					300	
Deduct for door way	2	3	5½	-	33	
Balance Sqrs						2.67
Concrete for the Top	Amp	Amt			Rs	4

Well.

Brick in Chunam						
Parapet-wall for the above	1	17	1½	3	76	C.Ft. 76
Plastering.						
All Around	1	17	6		102	Sq.Ft. 1-0.2
Bearing Slabs under-neath the parapet-	1	17	1½	(4")	25	Sq.Ft. 25
Upright-Slabs for drawing water	2	8	1½	½	12	C.F. 12
Wooden beam with pully &c across the upright-slabs for drawing water	Lump Sum					8
Sundry Repairs here & there	—	Do	—			7,

Abstract Estimate of the probable cost of repairing the Kalaseswara Swami Temple at Mandya.

Items		Per Rate	Qr	Cost	
Teak wood Shutters to windows	Sft.	-0-10-0	15	9	
Jungle wood doors as per details	each	8-0-0	2.	16	
Brick in Chunnam	cft.	-0-2-9	188.	32	
Plastering	Sqr	2-12-0	3.69	10	
Concrete	Lumpsum Rs			4	-
Bearing Slabs under neath the parapet	Sft.	0-3-0	25	5	-
Upright Slabs for drawing water	cft.	0-12-0	12	9	4
wooden beam as per details.	Ls. Rs			8	
Sundry repairs here & there				7	-
				100	
Total					100 - 0 - 0
Contingencies etc			5		5 - 0 - 0
grand total Rupees 105					105 - 0 - 0

(Sd) Krishna Iyer
Supervisor Gr 3
Sub Div

Mysore District — Memorandum Department — French Rocks Sub Division

Memo accompanying the Bills for Repairing the Jamarthana Swamy's Temple as well as that for Sahalaswara Swamy's Temple at Hanagya.

I. Jamarthana Swamy's Temple

A bill amounting to Rs 354-0-11 for the Civil works executed by Contractor Nyamburu is herein enclosed. All the works have been executed very Satisfactorily in accordance with the Sanctioned Estimate. A Lump Sum of Rs 50 had been provided for in the Estimate under the Sub Head Sundry Repairs, Such as white Washing, repairing the floor and Pointing the joints of Slabs &c, but during the execution of the Works it was found absolutely necessary for the Safety and Securness of the Structure to carry out Brick works in the wall Chunam Plastering and Burnt Stone Slabs for Drains to Drain off rain water and Bond Stones to the cracks in the walls as well as slabs both at the bottom and over the Teak wood windows &c now put in, and thereby the Lump Sum of Rs 50 has been slightly exceeded.

2. A detailed Estimate amounting to Rs 248-13-8, is also herein enclosed for Repairing the Thayar Samathi, which includes Rs 24/- for the Teak wood Pattened Door to be put in for Jamarthana Swamy's Temple, with a View to put the roof of Thayar Samathi perfectly water tight and other items as detailed in the

Estimate, utilizing the amount of Rs 100/- under Consecration for acquiring the building, as ordered. It could be seen from the Bill and from the Estimate of Thayar Sannathi, that the whole sanctioned amount of Rs 565/- will be exceeded only by Rs 37-14-7 or Rs 38/- in round figure, which amount is not much, considering the nature and quantity of works done to the Temple.

II.

Sri Kalasmara Swamy's Temple:-

A bill amounting to Rs 159-11-4 for the works executed by Anantha Rama Doss as against Rs 105/- as Sanctioned, is here in enclosed. All the works have been carried out very Satisfactorily, according to the Sanctioned Estimate. The Cause of excess of Rs 54-11-4 is entirely due to Mahathwara Gopuram, Constructed very neatly by Anantha Rama Doss and other Brahmin Community interested, fully hoping that the Honourable Secretary will be graciously pleased to Sanction this extra works also.

The H. S. is of opinion that this ornamental structure at the entrance of the Temple is very essential and Consequently begs to recommend that the extra amount may kindly be Sanctioned, Since the Brahmins who have undertaken this work, are

very friendly

extremely poor in Circumstance.

17-11-99.
Dravya

S-Bo, 2 Class
Supervisor
No 3 Sub Division

Sole I have inspected both the works and feel quite satisfied with their execution. I beg the privilege of increase over the sanctioned estimates & may kindly be sanctioned as the work have been executed fully anticipating sanction.

The work of the Tagarsannidhi was got & commenced while the other two works have been fully completed If the submitted estimates are sanctioned I shall see that the work is carried out as satisfactorily as the others

Yours
Dravya

Mulroy Fund French Rocks Darrscon

Cochin District

Measurements of works done for repairing and improving the Janardhana swamy's temple at Kandya

Subhead	Particulars of work	No.	Dimensions L	B	D	Contents	Total	Rate	Cost
By Contractor	Ye Kamberam pillu D/ 16 —	1	1-	9	9				
Teak wood windows	Fixing two Teak wood windows in the Ekavarungal 3'×4' with glass sutter inside and wooden shutters outside with iron bars 1" dia iron works & Painting Complete	2		&c		2	2	20 - -	40 - -
Ornamenting Concrete	walls for the above	sft 2	4½	2	3¼	63	63	- 3 -	15
	Flooring lower floor	1	29	8	¼	130			
	Do upper floor	1	29	6½	¼	47			
	Do Do	1	23	7	¼	40			
	Do Do	1	11	4	¼	11			
	Do Do	1	7	3	¼	5			
	Top of Dwajastumbo temple	1	41	26	¼	226			
	Total.					459			
	Deduction pillers	10	1	1	¼	3			
	Do	4	¾	¾	¼	1			
	Total deductions					4			
	Balance sft					—	455	- 2 6	71 1 0
Brick in lumam	parapet walls on the top temple	1	15	1	⅔	10			
	Do	1	5	1½	⅔	5			
	All round	1	108	1½	1½	243			
	Total sft					—	258	- 2 9	44 5 0
Plastering in lumam	parapet walls over the temple	1	108	-	4	432			
	All round the compound walls								
	North side	1	11	-	2	22			
	Do	1	70	-	3½	245			
	Do	1	8	-	6	48			
	Western side	1	20	-	4	80			
	Do	1	16	-	2	32			
	Do	1	50	-	5	250			
	Do	1	22	-	4	88			
	southern side	1	13	-	4½	58			
	Do	1	24	-	2¼	54			
	Do	1	44	-	4	176			
	Eastern side	1	16	-	4	64			
	Gate	1	2	-	2	4			
	Western side	1	40	-	2	80			
	Do	1	10	-	3	30			
	Southern side	1	32	-	3	96			
	petty here and there	L S				100			
	Total Sq ro					—	1860	2 12 -	51 2 5

Excavating foundn	For the new compound wall in													
Excavation	Continuation of the existing wall	1	17	2	4½	153	6	·	2	·				
Rough stone in Found	Filling in foundation for the above			do		153	153	·	1	3		15		
Brickwork in found	Superstructure	1	17½	1½	6	153	153	·	1	9	16	11	9	
Sundry Repairs	Repairs such as white washing repairing the floor and joining the joints of slabs &c													
White washing	Do Iswarajastumba mantapam	1	60	·	9	540								
	~~Dovadonga~~													
	Kavarangya	1	65	·	7½	488								
	pillers	1	86	·	8½	731								
	Gate	10	4	·	8½	340								
	do	2	27	·	10	540								
	Total Sqrs	1	19	·	10	190	28·29	·	4	·	7	1	2	
Cement painting	cofs of Kavarangya mantapam	1	22	21½	·	473								
	Do Iswarajastumba	1	40	24	·	960								
	Total Sqrs						14·33	1	8	·	22	7	11	
Brickwork	Inside of temple	1	3½	1½	7	37								
	Do	1	5	1½	1	7								
	out side	1	20	3¼	5	75								
	Total cft						119	·	1	9	13	·	3	
Brickwork in mortar	Rebuilding the damaged walls	1	6	1⅛	5	33								
	Do	1	2	1¼	¾	2								
Burnt stone slabs	Total						39	·	29		6	11	3	
	Bottom and lintel slabs to windows	2	4½	2¼	·	40								
	Bond stones to walls in Iswarajastumba temple	5	3	1¼	·	16								
		1	3	1½	·	4								
	Total Sqft						60	·	6	·	22	8		
Plastering in cement	Inside of the temple	1	63½	·	7½	466								
	Do	1	2¼	·	6¾	19								
	outside Do	1	39	·	8	312								
	Do	1	23	·	10	230								
	Do	1	20	·	2½	50								
	Do	1	7	·	6	42								
	Do	1	20½	·	4½	92								
	Total Sqrs					72·11	12·11							
	Deduction Doorways	1	5	·	7½	38								
	Balance Sqrs						11·73	2	12	·	32	4	2	
Stone Doniea	over the temple to take of water &c	2		&c		2	2	2	·		4	·	·	
Petty Repairs	such as removing debris Rubbish &c &c Lump Sum Rs-										10	·	·	
	Grand Total Rupees										354	·	11	

Certified the above measurements have been made by me and that the work has satisfactorily executed

W. Muttaiah Devayya
Taluk Surveyor

Assistant Engineer

Supervisor

Mazarry's Funds

Alypore District — French Rocks Sub.

measurements of works done for repairing the Sakleswaraswamy temple at Bandya

Sub head	Particulars of work	No	Dimensions L	B	D	Contents	Total	Rate	Cost
By Ahmed Baksh Carpenter	Quantity Rate & Cost as per Estimate of 28-9-99								
Allwood Letters Englewood doors	To the windows in front one Garbhagruhamukhi with iron works complete	2	2½	·	2	16	Sft 10	· 10	6 4
	Another for Vidyaswaraguhi with iron works complete	1	(6½ × 3⅓)			1			
		1	(4⅔ × 3⅓)			1			
	Total					Nos	2	8 8 · 16	·
	Narayanaswamy's temple								
Brick in Lime Mortar	All round the temple	1	12	1¼	8	120			
	Parapet walls on top	1	22	1/8	1½	37			
	Total					157			
	Deduct for door ways	1	5½	1¼	3	21			
	Balance					cft	136	· 2 9	23
Plastering	All round outside of temple	1	15	·	13	195			
	Do Inside do	1	7	·	5¼	37			
	Do do Compound wall	1	40	·	3	120			
	Do do do	1	38	·	1¾	66			
	Do do do	1	6	·	2	12			
	Do outside do	1	42	·	1¾	74			
	Do do do	1	42		2½	105			
	Total					Sqrs	6 09	2 12	13 1
Concrete	Top of temple Lumps Sum					Rupees			4
Cornice work	All round below parapet walls	1	25	R ft		25	25	· 6 · 9	
Do	Do parapet walls	1	25	R ft		25	25	· 4	6
Petty repairs	For repairing the floor of temple inside with concrete and flattening & here and there patch work Lumps	Sum				Rupees			2
	Drawing well								
Brick in Lime mortar	Parapet walls all round	1	20	1¼	3	75			
	Do for Bases	2	2¼	1	3	13			
	Total					cft	88	· 2 9	15 2
Plastering	All round Inside and outside	1	20	·	6	120			
	Bases at sides	2×2	1½	·	3	18			
	Total					Sqrs	1 38	2 12	3 6
Stone slabs	Bearing slabs underneath parapet	1	6½	1½	·	39	Sft 39	· 3 ·	7 5
Do	upright slabs for drawing water	2	8	1¼	½	10		·	
	Beam stone over upright stones	1	8¾	1⅝	½	6			
						cft	16	· 12 · 12	·

real	Brought forward			118	11 4
Wiring fully	Iron Railing complete	Lump Sum	Lump Sum Rupees		
Set of Ornamental Brackets					
Soffit Construction newly over the entrance door		Lump Sum	Rupees	40	
	Grand total	Rupees		159	11 4
	Deduct Extra work done than the Estimate			54	11 4
	Amount to be paid as per Estimate			105	

Certified that the above measurements have been made by me and that the work has been satisfactorily executed

28/9/99

Amildar
Mandya Taluk

Supervisor.
No. 3 Sub Division
Mandya

Muzrooy Fund

French Rocks Division Mysore District

Detailed Estimate of the Probable Cost Repairing Jayar Sannidhi of Janardhanaswamy's temple at Mandya from the amount available in the Estimate already sanctioned for the purpose and also the sub head Compansation

Sub head	Particulars of work	No	Dimension L	B	D	Contents	Total	Rate	Cost
Coomanthy	Parapet walls over the temple	1	122	3/4	1/4	114			
	Do	1	32	3/4	1/4	30			
	Total Cft						144	3	2 4
Brick Timbers Humaun	Rebuilding the above	1	154	1/8	1/4	217	217	29	37 4
	Do	1	154		3	462			
Plastering	Side walls on tops Rear & Sopurum	1	24		3	72			
	Verandah	2	6		8	96			
	Total Sqrs.						630	2 12	17 5
Concrete	over the temple	1	37	24	1/2	444			
	Do								
	Kotar Mantapum	1	24	8	1/2	96			
	Floor of temple	2	5	5	1/4	12			
	petty here and there	1	25	23	1/4	144			
		L S				25			
	Total Cft						721	2 6	112 10 6
Sunnam Pointing	For slabs underneath the roof	1	25	23		575			
	Do Do Verandah	1	23	8		184			
	Inside here and there	L S				200			
	Total Sqrs.						959	18	145 3
Repairing and white washing the Humaruum		Lump Sum					Rs		8
Stone Doors Teakwood doors	Teakwood doors battened with locks and required ironworks &c every thing complete								
	Jayar Sannidhi	1	6 1/2	4		26	26	1	26
	Swamy's Do	1	6	4		24	24	1	24
Cutting and removing roots entirely that are come into the building		Lump Sum					Rupees		5
	Grand Total Rupees								248 13 8

B.M. Muthaiah Sannaya
Sub Assistant

Supervisor
No 3 Sub Division
Mandya

W.D.M.
Amildar
Mandya Taluk

[Muz. 8A]

Muzrai Secretariat. File No. of 190

Dear Sir,

I beg to send herewith bills of work done & the Panchama. stores & tools for carrying out the estimate for repairs to Tyar tank. I shall commence work & the latter to be on receipt of further sanction. Please send the

checks & the con
tractors, who came
to Bangalore and
get their rates in
Rounds cashed at
the Huzur Treasury
they told me instead
of going at once there
they will go after
receipt of the Che-
ques as they have
some urgent pressing
work here.

I am leaving
this tomorrow by

[Muz. 8A]

Muzrai Secretariat. File No. of 190

and shall send the
Corrected bill of
the Vrindavanesha
temple after
it has been
passed by the same
Can you give me
a small sum
of Rs 20 to repair
the mutt of the
place when I was
visited it then
morning & find some
bright repairs are
necessary?
Yours truly
K. Narayana

[Muz. 8A]

Muzrai Secretariat. File No. of 190

File No.	of 190	Muzrai Secretariat.

No 566 Ex 2
Dy 6-12-99.

Amount sanctioned in Govt Pro No: 1190 dated 29th July 1899. Rs 565-0-0
Amount of this account Rs 37-14-7.
Now sanctioned Total Rs 602-14-7

Read:—.

Govt Pro No. 119 dated 29th July 1899 sanctioning an estimate amounting to Rs 565 for repairing the Sri Jayarthacca swami temple at Mandya.

order thereon:—.

Certain items of repairs not provided for in the above estimate being found necessary to the Thayar Sannidhi of the said temple, these latter repairs which are estimated to cost an additional outlay of Rs 37-14-7 are now sanctioned, the entire charge, namely Rs 602-14-7 as noted in the margin being met from the State Grant of Rs 15000 sanctioned for the repairs of minor Buildings in Govt Pro No. 1083 / Revx 7105-92 dated 29th March 1899.

2 A bill for Rs 354-0-11 being the actual cost of work done to the temple up to 18th November 1899. and [redacted] signed by the Inamdar Superintendent is forwarded to the Comptr for audit and return to this office, the amount being made payable at the Taluk Treasury at Inamdya where the temple is situated.

3. A copy of the measurement list on which the bill is based is also forwarded to the Comptr for reference.

Inamdar Secretary

To,
The Comptr & Govt
with the bill &
measurement list

Mnz A.]

The Government of Mysore ..... Dr.

Particulars.	Amount.	Remarks
On account of the repairs — executed to the Sri Janardhana- — Swami temple at Mandya —	354 .. 11	Vide Govt. Pro: no 119 d/ 29th July 1899
(To be made payable at the Taluk Treasury at Mandya)		

Bangalore,
Dated.. 6th December 1899

Dft A Rau
Muzrai Superintendent

Read:—.

Govt Pro No 120 D.
29th July 1899 Sanctioning
an Estimate amounting
to Rs 105 for repairing
the Sri ~~Kalaseo~~ Sakleshwara
Swami temple at Kandya.

---

order thereon:—.

No 567
Eu 2.
D 6.12.99.

Certain additional works
not provided for in the
above Estimate having
subsequently been found
necessary to the temple, the
same have been executed
at an extra cost of
Rs 54-11-4. This extra
charge of Rs 54-11-4 is
Sanctioned from the State
Grant of Rs 15000 provi-
ded for in Govt Pro No.
1083 D 29th March 1899.
Mwk 7 105-92
A bill for Rs 159-11-4.

being the actual cost
of the repairs executed
to the temple inclusive
of those sanctioned herein & Signed by the Joint Secretary
~~is accordingly countersigned~~
~~and~~ forwarded to the
Comptr for audit and
return to this office,
the amount being made
payable at the Taluk
Treasury at Nandya
where the temple is
situated.

2. A copy of the measure
ment list on which
the aforesaid bill is
based is also forwarded
to the Comptr for refee.

A
Joint Secretary

To, The Comptr of Accts
with the bill & copy
of measurement list

Government of Mysore ..... Dr.

Particulars.	Amount.	Remarks.
on account of the repairs executed to the Sri Sakleswara-swami temple at Mandya	159 11 4	Vide Govt Pro: no 128 dt/ 29th July 1899.
(To be made payable at the Taluk Treasury at Mandya)		

Bangalore,
Dated. 6th December 1899.

A1
Muzrai Superintendent

To,

Mr C V Narayana Rao

Amildar. Mandya.

D. O.

Your letter of 18th ultim. ~~forwarding two bills amounting to~~ reporting that works to the value of Rs 354-0-11 and Rs 159-11-4 ~~for the repairs~~ have been executed to the temples of Sri Janardhanaswami and Sakleshwaraswami respectively. I herewith send you two ~~separate~~ bills for those amounts duly audited by the Comptr for payment in the Mandya Taluk Treasury. Please have the money paid to the contractors and send their stamped receipts to this office for record.

2 The excess amount required for the repairs of the Thayar Sannidhi

to the Sri Jnanaprasuna-
Sannidhi Temple has also been
Sanctioned.
Please have this work
completed soon and send
a bill of costs to this
office for payment.

Yours.

PS

OFFICE OF THE DEWAN OF MYSORE
RECEIVED
No. 852

No 584

Yours faithfully,

Signature .....

Name .....

Address .....

.....

.....

Date 20/1/1900

Fin. 1]

FORM OF PAYEE'S RECEIPT.

Received this day of 189 from Officer in charge of Treasury at

ಈ 1899 ನೇ ಇಸವಿ [illegible] ಅಂಶವು 31 ನೇ [illegible] ದಿವಸ [illegible] ಖಜಾನೆಯಲ್ಲಿ. ಸ್ವೀಕರಿಸಿದ

ಅಧಿಕಾರಿಯಿಂದ

Rupees (354-0-11) [illegible]

on account of

ಸಂಬಂಧ [illegible]

Examined and entered

Treasury Accountant

Pay Rs 354-0-11

Treasurer [illegible]

Payee's signature

Countersignature

Receipt stamp for sum above Rs. 20

Fin. 1]

FORM OF PAYEE'S RECEIPT.

Received this day of 189 from Officer in charge of Treasury at

ಈ 1894ನೇ ಇನಿ ತಿಳಿಂಬಳ ಒಂಬತ್ತು ತಿಂ ಮಾಸದ ಆ ದಿನ ಕಲ್ಲಿಕ್ಟರ ಸಾಹೇಬರ ಕಛೇರಿಯಲ್ಲಿ ಕೊಟ್ಟ

ಪಾಡುಳ್ಳ ಒಂದು

Rupees (159-11-4) ನೂರ ಅರವತ್ತೊಂಬತ್ತು ರೂಪಾಯಿ ಹನ್ನೊಂದು ಅಣೆ ನಾಲ್ಕು ಪಾಯಿ

on account of ಸಾಲ್ಟ್ ಕಛೇರಿಯ ಕಲೆಕ್ಟರ ಸಾಹೇಬರ ಆಜ್ಞೆಯಂತೆ ಕೊಡಗಿನ ಪಾಲೆಕಾಡ ತಾಲೂಕಿನ ಕಾಲ್ಪಿಕಾಡಿನಲ್ಲಿ ಕಾಲ್ಪಿ ಕಡಿಯುವದಕ್ಕೆ ಕೊಟ್ಟ

Receipt stamp for sum above Rs. 20.

ಅಂಚೆಯ ಚೀಟಿ

ONE ANNA

Examined and entered

Pay Rs. 159-11-4

Payee's signature

ಪಾಡುಳ್ಳವನು ಮಾಡಿದ ಗುರುತು

Treasury Accountant.

Treasury Officer.

Muz. 10]

ನಂ. 581

ಮೈಸೂರು ಸಂಸ್ಥಾನದ ಮುಜರಾಯಿ ಸುಪರಿಂಟೆಂಡೆಂಟರವರ

ಮುಜಾರ ಕಚೇರಿನಿಂದಾ.

ಮಂತ್ರ ತಾಲ್ಲೂಕು ಅಮಿಲರಿಗೆ.

ಮಂತ್ರದಕ-ನಿಬಿಂದಲ್ಲಿರಲು ವಿಚಾರದಲ್ಲಿ ಸ್ವಾಮಿಯವರದೇವಸ್ಥಾನ ಶ್ರೀ ಆಕಾಶ- ಲೀಶ್ವರ ಸ್ವಾಮಿಯವರದೇವಸ್ಥಾನಗಳು ಇದೇವಸ್ಥಾನಗಳಲ್ಲಿ ಯಲಾಂ ಶ್ರೀಮಂತಿಶಿವ ಕಾಂಗಾಂದಿಗಳಿಗಾಂ ಶಿಮಂತ್ರ ಕಾಲ್ಲಾಂಶಿಲುಶ್ರೀಚರಿಮಿಲಿತಿಶಿಯಂಯಾರ್ಜಿತಿಶಿವ ಲಲಾಂ ಮಾಂಗಿಲ್ಲಿನಲ್ಲಿನಮಲಾಂಶಿಲುವಿ ಲಿತಿಲಿ ಶ್ರೀಚಿಲ್ಲಿಗಳಿಗಿ ಜ್ರೀಂದಿತಿಶಿಂಬ ರ್ಕಿಂಗಳಲು ಇವಿನಿಶಿಂರಿವಿನಲ್ಲಿಂಲಿಲಿದಿಲ್ಲಿ ಜ್ಞಿಗಿಶಿಲಿಗಳಲು ಸಿಶಿಶಿಲುವದಲ್ಲಿದಿಕದರಿಲಾಂಚಲಿ ಗನ್ನ ಲಿಯಾಂಯಾಂಕಂಪ್ರಾರ್ಥಿಲ ದಾಂತ್ರಿಗಿ ಶಿಂತ್ರಿ ಪಾವಶಿವಾಂತಿಶಿ ಅವಲಿಗಳಲ್ಲಿಂದ ರಶೀದಿಗಳಲ್ಲಿ ವಿತದು ಅವುಗಳನ್ನಾವಿ ತಿಬಿಚ್ಚಿ ಲಾಂ ಲಿಪ್ಪಿ ಶಿಶಿರಾಂಗಿಕ ಚೀಶಿಂದಲಿಕಡಿಗ ರಶಿಗಿನ್ನ ಅದರಂಶಿಕಡಾಪಾವಶಿವಾಂತಿಶಿದ್ದ ಶ್ರೀ ಅಧಿಕಾರಿಗಿಳಿಂದ ರಶೀದಿಗಳುಶರದಿರಲಿವ ದಿಲ್ಲಾ- ಉಪ್ಪಾಪಾವಶಿವಾಂತಿದ್ದನಿಶ್ರೀರಶೀದಿಗಳ

ಇಲ್ಲಿಂದ ಸ್ವಾಂತಿಲಾಲು ಪರಿಪ್ಪಿಗಿಲು ಕಿವಿಗಾರಂಬಿಲು ಕಿವಿಗಿ-೧೧-೧೯೪೪ ಲಿ ಶ್ರೀ-ಲೀಶ್ವರಸ್ವಾಂಮಿಯವರ- ತಿಲಿಂಗಿ ——— ೧೯೪೪-೧೧-೪

ఇది సరిచేసి మళ్ళీ మీ అంతర్గత విజిలెన్స్ అధికారులకు
పంపించండి -

తేదీ 20 లోపల 1500 చదరపు అడుగులలో

Thoraipalayam Superintendent

21-1-1900

W.O. 1066

ఆ మాదిరిగా

తేదీ 22-1-900

Sakkarai

12/8/20

about June 17th —



No. 258 dt 11-9-1900.

F 4-1

[illegible] 846 [illegible]
20-8-00

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

7/9/00

1902

From A. Ramanuja Iyengar Esq^r
off^g Deputy Commissioner
Mysore Dist^t

To L. Anandasami Rao Esq^r BA
Deputy Secretary to Govt.
Dated 11th } in Mysore Dept.
Despatched } April 1902
Received

General No. 309
No.

Enclosure No. one



Submitted

The Estimate may be sanctioned and the Savings Bank book may be called for for information

Rs
12/4/02

Has the honor to forward herewith for sanction an Estimate for Rs 90/- for repairing the building used for keeping the car or Ratha of Sri Janardana Swami temple in Mandya. The cost can be met from the sum of Rs 228-6-a at the credit of the temple in the Savings Bank —

I am Sir
Your Obedient Servant
A. Ramanujaiengar
Dy Commissioner
Mysore Dist

Proceedings of the Government of Mysore.

READ :—

Docket No. 309 dated 11th April 1902, from the Deputy Commissioner, Mysore District, submitting for sanction an Estimate amounting to Rs. 90/- for repairing the building used for keeping the car of the Sri Janardana swami temple at Mandya.

ORDER THEREON.—No. 1740-1 Ecl 1.
Dated Bangalore, Mucr 48-96 7th May 1902 ~~189~~.

The Estimate is sanctioned, the cost, *viz.*, Rs. 90-0-0 being ~~debited as follows:—~~ met as proposed by the D/Commr. from the ~~Savings~~ sum of Rs 228-6-0 available in the Govt. Savings Bank, at the credit of the Mahar.

2 The D/Commr. is requested to submit the Savings Bank Book of the Mahar for the information of Govt.

27/4/02
D/ Muzrat Secretary
Muz. Dept.

To—The Deputy Commissioner, Mysore District, with the sanctioned Estimate ~~and other enclosures.~~ for information,

The Comptroller to the Government of Mysore, ~~with a copy of the Abstract Estimate and~~ Treasury Officer's Certificate.



1902

From H.T. Ramanujiyangar Esquire
Offg Deputy Commissioner,
Mysore District.

To L. Anantaswami Rao Esquire B.A
Deputy Secretary to the Govt
of Mysore, Muzrai Deptt.

Dated 20th } May 1902.
Despatched }

Received

General No. 334
No.

Enclosure No. 1 H.V.P.

I have the honor to submit herewith for sanction an estimate for Rs 110/- for repairing the Kitchen attached to the Sri Janardanaswami temple Mandya, received with the French Rocks Sub Division Office yadi No 1601 dated 20th April 1902.

The cost may be met from the sum of Rs 244-100 at the credit of the temple in the Savings Bank.

I have the honor to be
Sir
Your most obedient servant
For Offg Deputy Comm
Mysore Dis

TH

22/5/02

Submd

may be sanctioned.

The Savings Bank Pass book may be sent for for reference

Rs

22/5/02

READ :—

Docket No. 334 dated 20th May 1902 from the Deputy Commissioner, Mysore District, submitting for sanction an Estimate amounting to Rs. 110/— for repairing the Kitchen attached to the Sri Janardhanaswamy Temple at Mandya.

ORDER THEREON.—No. 1970-1 — En 1478 P 1
Inam 48-96 June
Dated Bangalore, 4th ~~May~~ June 1902 ~~189~~

The Estimate is sanctioned, the cost, *viz.*, Rs. 110 — — — being debited ~~as follows:—~~ to the savings of Rs 244-10 — reported to be available at the credit of the temple, and remaining invested in the Savings Bank.

2. The D/Commr is requested to submit for reference the Savings Bank Pass Book ~~for the amount standing to the credit of the temple~~ referred to in his D/Ltr.

D/1-

Js

By ~~Murrai~~ Secretary,
Mmz. Dept.

To—The Deputy Commissioner, Mysore District, with the sanctioned Estimate ~~and other enclosures.~~

The Comptroller to the Government of Mysore, with a copy of the Abstract Estimate and Treasury Officer's Certificate. (Extract from the Amildar's Report).



190 [illegible]

From [illegible]

To [illegible]

Dated [illegible]

Despatched

Received

General No. [illegible]
No.

Enclosure No. [illegible]

Rec'd
5/9/04
[illegible]

Deputy Commissioner's Office
Mysore District
Inam Department
Dated Mysore 5th September 1904

To
V. Ananthasami Pao Esq BA
Secretary to the Government of
Mysore in the Inam department

Sir,

I have the honour herewith the correspondence ending with yadi no 41 dated 7th July 1904, from the Assistant Commissioner in charge of the Heggadadevana Kote Division, I have the honour to state that Yekamba Bhay appears to have repaired the Janardhana swamy temple at Nandya and received a sum of Rs 357-11, leaving a balance of Rs 233 2 10. She has been frequently praying to pay the amount. The work was carried out at the instance of the late Inam Secretary and part of the money was also sent to the builder of Nandya directly from your office.

I therefore request that the balance of Rs 233-2 10 may also be kindly ordered to be paid to him.

I have the honour to be,
Sir,
Your most obedient servant

Dy Commissioner
Mysore District

Mysore

Read:-

Govt Pro. no. 119, dy 29th July 1899, sanctioning an estimate amounting to Rs 565/- for repairing the Sri Janardhana Swami Temple at Mandya.

(2) Govt P.O. no 566, dy 6th December 1899, sanctioning an additional sum of Rs 37 14 7, for certain further repairs needed ~~to the above and~~ to the ~~Top~~ Jaya Sannidhi of the temple, and countersigning a Measurement bill for Rs 354-0-11 for works already executed.

~~(2) Govt Pro No 566~~

And,

(3) Letter no. 72, dated 2nd September 1904, from the Deputy Commissioner, Mysore Dt, submitting a second measurement bill for Rs 233-2-10, for the repairs executed to the Institution

---

Order thereon

no: 1422-3, Encls 1 & 17-6, dy 10th October 1904.

The second Measurement bill is above referred to is countersigned and forwarded to the Comptr for audit and

return to the Deputy Commr.
for payment, the charge being
met from the State Grant
of the current Offe year

5/10/04

Secretary,
Muz: Deptt

7/5/04

To
The Dy Commr, Mysore Dt, ~~with the bill~~
Tel & enclosures
Comptr, Mysore Govt, with the bill

2421

190

From

To

Dated

Despatched

Received

General No.

No.

Enclosure No.

Deputy Commissioner's office
Mysore district
Muzrai department
Dated Mysore -- December 1904.

L. Anantasami Rao Esq, BA
Secretary to the Government of Mysore
in the Muzrai Department.

Sir,

Adverting to Government Proceedings No. 1970-1 / 48-96 dated 4th May 1902 sanctioning an estimate amounting to Rs. 110-- for repairing the Kitchen of the Sri Janardhanaswami temple at Mandya, I have the honor to state that the Amildar reports that he was not able to carry out the work as per estimate sanctioned and has submitted 2 marginally noted estimates amounting to Rs. 95/- and 37/- respectively.

2 The Divisional Officer also supports the Amildar's proposal.

3 I therefore request that Government may be pleased to sanction the above, the cost being met from the amount of Rs. 225-14-2 deposited in the Government Savings Bank in the name of the temple.

4 The connected records are here with submitted. × submitted R. I. R. No. 63297 14 Nov

I have the honor to be
Sir,
Your most obedient servant
V. N. Narasimha Iyengar
Deputy Commissioner
Mysore district.

× 1. Estimate for repairing the Kitchen Verandah of Sri Janardhanaswami temple at Mandya. Rs. 95-0-0
2 Do ——— Kitchen & Attached & P ——— Do ——— 37/-

Muzrai

Read:—

Govt Pro: No 1970-1
Muzt 48 96'
dated 4th June 1902, sanctioning an estimate for Rs 110/ for repairing the kitchen ~~of~~ attached to the Sri Janardanaswami temple at Mandya

And,

Letter No 191, dated 26th December 1904, from the Deputy Commissioner, Mysore District, reporting that the works sanctioned above were not carried out, and submitting for sanction 2 fresh estimates — one for Rs 95/- for repairing the Vahana Verandah and the other for Rs 37/- for repairing the kitchen of the temple

— " —

Order thereon
No: 2771-2 Encls 2 & 17/6 and two,
Dy 31st Jany 1905 —
The two Estimates aggregating Rs 132/- are sanctioned, the charge being met from the sum of Rs 225-14-0 reported to be available

at the credit of the temple and

invested in the Savings Bank.

2 The Estimate for Rs 110/- sanctioned

in Govt Pro: of the 4th June 1902, read

above, is hereby cancelled.

27/1/05

Secretary;

Muz: Deptt.

To

The Deputy Commr:, Mysore Dt,

with the sanctd Estimates & other enclos:

& Comptroller, Mysore Govt,

with a copy of the Abs: Estimates